



ENDOSCOPY SERVICES

Competitive prices in today's economy to meet your needs

FLEXIBLE REPAIR LIST

- Bending Rubber Replaced
- C-Cover Replaced
- Light Guide Lens Replaced
- Objective Repaired (Negative Lens Replaced)
- Air/ Water Nozzle Replaced
- Air/water Channel Replaced in Insertion Tube / Light Guide Tube
- Biopsy Channel Replaced
- Suction Channel Replaced in Light Guide Tube
- Auxiliary Channel Replaced
- Elevator Irrigation Channel Replaced
- Light Guide Fiber Bundle Replaced
- Insertion Tube Mounting Bracket Replaced
- Insertion Tube Boot Replaced
- Insertion Tube Replaced
- Insertion Tube Dent Removed
- Boot Extender Installed
- Light Guide Tube Replaced (Fiberscope)
- Light Guide Tube Replaced (Video)
- Light Guide Tube Dent Removed
- Light Guide Tube Boot Replaced @ Control Body
- Light Guide Tube Boot Replaced @ Electrical Connector
- Right/Left Knob Internal Repair
- Right/Left Control Knob Replaced
- Up/Down Knob Internal Repair
- Up/Down Control Knob Replaced
- Switch #1 Replaced
- Switch Wire Replaced
- Switch #4 Repaired/ Replaced
- Switch Head Repaired/ Replaced
- Angulations Adjusted w/Stoppers
- Bending Section Mesh Replaced
- Bending Section Replaced
- Coil Pipe Replaced
- Angulations wire Replaced
- Angulations System Overhauled w/Angulations Wire and Coil Pipe Replace/Mesh
- Electrical Connector Overhauled
- Video Pin (4) or more (Burndy) Replaced
- ETO Valve Assembly Replaced
- CCD chip replaced

Thank you for choosing Elite Endoscopy Services for all your repairs.

Office: 954-543-4333

Fax: 954-543-4331

info@eeservicescorp.com

www.ELITEendoscopyservices.com